

34010110115

014933

US EPA RECORDS CENTER REGION 5



514683

0-102R-P

INTER-OFFICE CORRESPONDENCE

REPUBLIC CREOSOTING COMPANY

DIVISION OF REILLY TAR & CHEMICAL CORPORATION

TO: H. L. Finch - Office

OFFICE: St. Louis Park

FROM: W. H. Barton

DATE: August 9, 1971

SUBJECT: Plant Safety Inspection

An inspection of the plant, with respect to safety and housekeeping, was made on August 5, 1971 with MESSRS. Keprios, Justin, and Lindberg.

The following areas need more attention:

1. Scrap around the dinky barn.
2. Scrap inside the incisor building.
3. The south end of the lumber yard needs a light sand covering where oil has been dumped on some weeds.
4. The sand dike near the settling basin should be removed to the low ground adjacent to it.
5. There are a few holes around the refinery that should be filled.
6. The safety stop in the mill has to be repaired so it will again operate by air pressure.

Very truly yours,

W. H. Barton

W. H. Barton

WNB:sjj

301086